

DOKUMENTASI

Infrastruktur Semenisasi Jln. *Gajah Mada* Gg. RT. 1
uk. Panjang= 91 mtr, Lebar 3,00 mtr, Tebal 10 cm

SEBELUM



SESUDAH



Pembuatan Gapura Jln. Gajah Mada Gg. 2 RT. 2
uk. Tinggi = 2,70 mtr, Lebar 3,25 mtr

SEBELUM



SESUDAH



Infrastruktur Perbaikan Drainase Jln. Mutiara Gg. 1 RT 7 Uk. Panjang = 64 mtr, Lebar = 3 mtr, Tebal 10 cm	SEBELUM	SESUDAH
	 A photograph showing a narrow, unpaved drainage ditch on the side of a road. The ditch is filled with debris and has a rough, uneven edge. A black motorcycle is parked on the road to the left of the ditch. In the background, there are buildings and a yellow banner with red and blue text.	 A photograph showing the same drainage ditch after it has been improved. The ditch is now paved with a smooth, light-colored material, and the edges are finished with a concrete curb. A black motorcycle is parked on the road to the left of the ditch. In the background, there are buildings and a yellow banner with red and blue text.

Infrastruktur Semenisasi Jln. KH. Abul Hasan Gg. 9 RT. 10 uk. Panjang= 68 mtr, Lebar 2,00 mtr, Tebal 10 cm	
SEBELUM 	SESUDAH 